TAS 24-18A / D214977 Verona Maintenance - Municipal Sewer / Water Connections at I-90, MP 252.71 in Onieda County

QUESTIONS AND ANSWERS

- Q1. I am contacting you for some clarification. The sewer lift station piping is called out as DIP. I assume meaning Ductile Iron Pipe. I cannot provide 2" DIP it is not manufactured. Can an alternate piping be used? Such as Sch80 pvc?
- A1. Schedule 80 PVC is acceptable.