

TAS 23-18 / D214923

Pavement Repairs at Various Locations in Syracuse Division in Seneca and Ontario Counties

QUESTIONS AND ANSWERS

- Q1. While reviewing the quantity workups, I noticed that in the quantity workup for the 12.5mm top item, that there is 623 ton noted for the full depth repairs. Per the provided detail, it looks like were just bringing binder to grade. The only repairs that should get top are the ones in the single course treatment area. Can you confirm whether we are or are not placing top at the FDR locations outside of the single course mill and overlay areas?
- A1. In the non-milled areas where FDR's are located, 12.5 mm top course shall be placed.