

TAB 24-25 / D214983

**1R Mill and Inlay between MP 351.40 and MP 378.20
in Monroe and Genesee Counties**

QUESTIONS AND ANSWERS

- Q1. In the typical sections on TYP-1 and TYP-2 the limits for item 404.1272 are shown to include the right shoulder. The quantities in the proposal seem to indicate that the 10' shoulder is included under 404.1252 instead of 404.1272. Can you please clarify under which pay item will we get paid for paving of the right, 10' shoulder.
- A1. In a typical two-lane configuration, the right shoulder shall be paved via Item 404.1252. At locations with a ramp lane (acceleration / deceleration) the ramp as well as left and right shoulder of the ramp shall be paved via Item 404.1272.